

11049A

11050A

11051A

THERMAL CONVERTERS



OPERATING AND SERVICE MANUAL

HEWLETT  PACKARD**CERTIFICATION**

The Hewlett-Packard Company certifies that this instrument was thoroughly tested and inspected and found to meet its published specifications when it was shipped from the factory. The Hewlett-Packard Company further certifies that its calibration measurements are traceable to the U.S. National Bureau of Standards to the extent allowed by the Bureau's calibration facility.

WARRANTY AND ASSISTANCE

All Hewlett-Packard products are warranted against defects in materials and workmanship. This warranty applies for one year from the date of delivery, or, in the case of certain major components listed in the operating manual, for the specified period. We will repair or replace products which prove to be defective during the warranty period. No other warranty is expressed or implied. We are not liable for consequential damages.

For any assistance contact your nearest Hewlett-Packard Sales and Service Office. Addresses are provided at the back of this manual.



OPERATING AND SERVICE MANUAL

(HP PART NO. 11049-90000)

MODEL
11049A, 11050A, 11051A
THERMAL CONVERTERS

Copyright Hewlett-Packard Company 1967
P.O. Box 301, Loveland, Colorado, 80537 U.S.A.

Model 11049A

TABLE OF CONTENTS

Paragraph	Page
1. General	1
3. Specifications	1
4. Calibration	2
6. Circuit Description	2
9. Applications	3
10. Output Measurements	3
14. Frequency Response Measurements	3
16. Generating an Accurate Calibration Signal	4
22. Maintenance	6
23. Thermal Converter Calibration	6
25. Repairing the Thermal Converter	7
37. Replaceable Parts	10

LIST OF TABLES

Number	Page
1. Calibration Accuracy	1

LIST OF ILLUSTRATIONS

Number	Page
1. -hp- Model 11050A Thermal Converter	1
2. Thermal Converter Schematic Diagram	2
3. Input-Output Relationship	3
4. Frequency Response Measurements	4
5. Test Signal Generation	5
6. Thermal Converter Calibration	6
7. Selection of R2	8
8. Selection of R1	8
9. Proper Orientation of Components	9
10. Replaceable Parts	11




Figure 1. -hp- Model 11050A Thermal Converter

1. GENERAL.

2. The -hp- 11049A, 11050A, and 11051A Thermal Converters accurately convert ac input signals to dc voltages proportional to the rms value of the input. They have essentially a flat response from 5 Hz to 10 MHz, and good frequency response from 10 MHz to 100 MHz. Table 1 shows the frequency response specifications of the thermal converters.

3. SPECIFICATIONS.

MAXIMUM INPUT VOLTAGE:

11049A: 3 volts rms
 11050A: 1 volt rms
 11051A: 0.45 volt rms

INPUT IMPEDANCE: $50 \Omega \pm 0.15 \Omega$ to 10 MHz

OUTPUT IMPEDANCE: less than 10Ω

OUTPUT VOLTAGE FOR FULL SCALE INPUT:

Nominal 7.5 mV

Table 1. Calibration Accuracy

Frequency Range	With Reference to Standard	Measurement Uncertainty
5 Hz to 20 Hz	within $\pm 0.05\%$	$\pm 0.12\%$
20 Hz to 20 kHz	within $\pm 0.01\%$	$\pm 0.02\%$
20 kHz to 50 kHz	within $\pm 0.01\%$	$\pm 0.03\%$
50 kHz to 1 MHz	within $\pm 0.01\%$	$\pm 0.06\%$
1 MHz to 10 MHz	within $\pm 0.05\%$	$\pm 0.12\%$
10 MHz to 30 MHz		$\pm 0.25\%$
30 MHz to 60 MHz		$\pm 0.50\%$
60 MHz to 100 MHz		$\pm 1.50\%$

OPTION 01: Includes calibration to 60 MHz and correctional data sheet covering frequency range from 5 Hz to 60 MHz.

OPTION 02: Includes calibration to 100 MHz and correctional data sheet covering frequency range from 5 Hz to 100 MHz.

Model 11049A

Page 2

4. CALIBRATION.

5. The Hewlett-Packard Standards Laboratory supplies a calibration report on each thermal converter with a statement of traceability to the National Bureau of Standards, and also supplies correctional data with each Option 01 or Option 02 Thermal Converter. The correctional data is based on the thermal converter's comparison with a known reference thermal converter, and when used with the thermal converters, eliminates all inaccuracies except the measurement uncertainties listed in Table 1. If no correctional data is used, the maximum inaccuracy is the sum of the values listed in the "with reference to standard" and "measurement uncertainty" columns in Table 1.

6. CIRCUIT DESCRIPTION.

7. The heart of the Thermal Converter is a $90\ \Omega$ UHF thermoelement containing a heater filament and a thermoelectric junction. The ac current into the thermoelement heats the filament, and the thermoelectric junction generates a dc voltage proportional to the filament heat. Therefore, the voltage out of the thermal converter is proportional to the input power. Resistor R2 adjusts the current through the thermoelement to 5 mA with a full scale input, and R1 adjusts the input impedance to $50\ \Omega$.




Figure 2. Thermal Converter Schematic Diagram

8. Since the output voltage is a function of input power, the output varies as the square of the input. If the input is doubled, the output will be four times as great; if the input is halved, the output will drop to one-fourth. For input changes of less than 3%, the input-output relationship is essentially linear; and the percent output change is equal to twice the percent input change. The following formula shows the relationship.

$$\% \text{ input change} = \frac{\Delta E_{dc}}{2E_{dc}} \times 100$$

where E_{dc} = thermal converter output voltage

Figure 3 shows the input-output relationship.




Figure 3. Input-Output Relationship

9. APPLICATIONS.

10. OUTPUT MEASUREMENTS.

11. The accuracy and sensitivity of thermal converter measurements are dependent on the accuracy and resolution of the output measuring circuit. Figure 4 shows a very stable and sensitive output monitor circuit. With this circuit, an output change of $1.5 \mu\text{V}$, or 0.01% of full scale, can easily be resolved. The

battery powered reference supply generates a stable reference voltage, opposing the thermal converter output; and the dc null meter monitors the difference voltage. The battery's short term stability is good enough that the thermal converter output changes may be read directly on the null meter without taking reference voltage drift into consideration. Another stable and accurate output measuring device would be a high resolution digital voltmeter or differential voltmeter. In order to resolve an input change of 1% of full scale, the output monitor should be able to resolve 0.15 mV ; for an input change of 0.1% of full scale, it should be able to resolve $14 \mu\text{V}$.

12. To build the reference supply shown in Figure 4 on the next page, use a mercury battery and wirewound resistor. The potentiometers should be 10 turn or 20 turn, and the switch should have low thermal contacts. After constructing the reference supply, place it in a shielded container and allow the mercury battery to age in the circuit for about a week. The longer the battery is allowed to age, the better its short term stability will be.

13. All thermal converter measurements should be made at a constant ambient temperature. Since the thermoelement responds to the heating effect of the input, any change in ambient temperature would cause a slight change in the thermal converter output.

14. FREQUENCY RESPONSE MEASUREMENTS.

15. Figure 4 on the next page shows a test setup for making simple but accurate frequency response measurements. The following steps describe the measurement.

Model 11049A

Page 4

CAUTION

DO NOT EXCEED THE RATED INPUT OF THE THERMAL CONVERTER. ALWAYS REDUCE THE INPUT BEFORE CHANGING FREQUENCY RANGE OF CIRCUIT UNDER TEST. ANY OVERLOAD OR HIGH VOLTAGE TRANSIENT MAY DESTROY THE THERMOELEMENT.




Figure 4. Frequency Response Measurements

- Set oscillator and reference supply levels to minimum.
- Connect null meter, reference supply, and thermal converter as shown in Figure 4. Keep cables connecting oscillator and thermal converter as short as possible.

- Adjust oscillator amplitude for a null meter indication of about 7 mV.
- Adjust reference supply for null indication within 1 μ V. Once null is obtained, do not readjust oscillator amplitude or reference supply output.
- Change frequency and note thermal converter output changes. Remember that percent converter output change equals twice percent input signal change.

16. GENERATING AN ACCURATE CALIBRATION SIGNAL.

17. The test setup in Figure 5 on the next page generates a test signal that may be used for both frequency response and absolute value calibration at any frequency within the thermal converter range. A dc standard acts as the absolute value reference, and a stable test oscillator generates the calibration signal. With S1 set to the DC position and the dc standard output set to the desired calibration voltage, the reference supply is adjusted for a null indication on the null meter. Then S1 is switched to AC, and the oscillator output is adjusted to reestablish a null indication. This sets the rms value of the oscillator output equal to the dc standard output. The oscillator output goes to the instrument under test.

18. DC REVERSAL ERROR.

19. DC inputs of opposite polarity will produce slightly different outputs from the thermal converter, and the

difference in outputs is called the dc reversal error. The dc reversal error is usually less than 0.05% and doesn't affect most measurements, but it should be compensated to achieve maximum accuracy. Instructions for compensating dc reversal error are included in the following calibration procedure.

20. CALIBRATION PROCEDURE.

21. The following steps describe a procedure for generating 1 volt calibration signal that is flat within the thermal converter specifications. Steps c through f describe the procedure for compensating dc reversal error.

NOTE

If the instrument under test is average or peak responding, use a low distortion test oscillator. A thermal converter and an average responding circuit react differently to distortion, and any distortion present will create a calibration error between the thermal converter and the instrument under test.

- Set test oscillator and dc standard outputs to minimum.
- Connect dc standard, test oscillator, thermal converter, reference supply, null meter, and instrument under test as shown in Figure 5. Keep all connections as short as possible.




Figure 5. Test Signal Generation

- Set switch S1 in Figure 5 to DC, and set dc standard output to +1.000 vdc.
- Adjust reference supply for null indication within less than $1 \mu\text{V}$. Record null meter indication (_____). Once null is obtained, do not readjust reference supply output.
- Reverse polarity of dc standard output and record null meter reading (_____).
- Set S1 to AC and set oscillator frequency to 10 Hz.

Model 11049A

Page 6

Adjust oscillator output so that null meter indication is half way between indications recorded in steps d and e. This sets oscillator output to 1 volt rms.

- g. Record error of instrument under test.



DO NOT CHANGE OSCILLATOR FREQUENCY RANGE WITHOUT FIRST LOWERING OSCILLATOR OUTPUT. SWITCHING TRANSIENTS MAY DESTROY THERMOELEMENT.

- h. Adjust frequency to next desired test frequency. Then readjust oscillator output for same indication as in step f. Record error of instrument under test.
- i. Repeat steps g through i for each test frequency desired.

22. MAINTENANCE.

23. THERMAL CONVERTER CALIBRATION.

24. Figure 6 shows the setup for calibrating a thermal converter to an NBS calibrated reference thermal converter. With this setup, the thermal converter can be calibrated to within $\pm 0.005\%$ of the reference thermal converter. The following steps describe the calibration procedure.

- a. Set test oscillator and both reference supply outputs to minimum.




Figure 6. Thermal Converter Calibration

- b. Connect both thermal converters, both reference supplies, both null meters, and the test oscillator as shown in Figure 6. Keep connections to thermal converters as short as possible.

- c. Adjust the oscillator amplitude for an indication of about 7 mV on both null meters. Set the oscillator frequency for 1 kHz.
- d. Adjust both reference supplies for null indications on their respective null meters.
- e. Change the oscillator frequency to 5 Hz.
- f. Readjust the oscillator amplitude for a null indication on the null meter connected to the reference thermal converter. The null meter connected to the thermal converter under test should read the same as the reference null meter. If not, record the error. Remember, the percent change in the thermal converter output is equal to twice the percent change in the input.
- g. Repeat steps e and f at 50 Hz, 500 Hz, 5kHz, 50 kHz, 500 kHz, 1 MHz, 3 MHz, 6 MHz, 8 MHz, 10 MHz, 20 MHz, 30 MHz, 40 MHz, 50 MHz, and 60 MHz. In each case, record the error.
- h. Use the error data collected in the previous steps to make corrections whenever using the thermal converter. If the difference between the reference thermal converter and the thermal converter under test is greater than the specifications in the "with reference to standard" column in Table 1, the thermal converter is not operating properly. Refer to repair instructions in paragraph 25.
- i. The calibration of a thermal converter should

be checked against an NBS reference thermal converter at least once every six months during the first year, and once a year thereafter.

25. REPAIRING THE THERMAL CONVERTER.

26. If the thermal converter is out of calibration below 10 MHz or if it has no output, the UHF thermoelement should be replaced. Since the values of R1 and R2 in Figure 2 depend on slight variations in thermoelement characteristics, they must be reselected when the thermoelement is replaced.

27. SELECTION OF R2.

28. R2 adjusts the current through the thermoelement to 5 MA with a full scale input. In the 11049A, R2 is made up of two resistors with a total value of about 510 Ω . In the 11050A, R2 is about 110 Ω , and in the 11051A, R2 is deleted. R2 should be a 1/2 watt, $\pm 5\%$ metal film resistor.

29. Figure 7 on the next page shows the test setup for selecting R2. The power supply generates a known input, and the dc voltmeter monitors the thermoelement output. R2 is selected to adjust the thermoelement output to 6.5 mV with 90% full scale input. Proceed as follows.

- a. With the power supply off, connect the power supply, thermoelement, dc voltmeter and an initial value of R2. For 11049A, R2 should be a 240 Ω and 270 Ω resistor connected in series. For 11050A R2 should be a 110 Ω resistor.

- b. Using voltmeter as a monitor, slowly adjust power supply output to 0.9 volts for 11050A or 2.85 volts for 11049A.
- c. Connect voltmeter to thermoelement. Output should be $6.5 \text{ mV} \pm 0.3 \text{ mV}$. If output is high, increase R2; if output is low, decrease R2.

30. An alternative but not as accurate method of selecting R2 is to assume that the thermoelement resistance is 90Ω and select R2 as 510Ω for the 11049A and 110Ω for the 11050A. If this method is used, the nominal 7.5 mV output may be high or low by as much as 10%.




Figure 7. Selection of R2

31. SELECTION OF R1.

32. R1 shunts the series combination of the thermoelement and R2 to adjust the input resistance to $50 \pm 0.15 \Omega$ and is made up of two approximately equal resistors connected in parallel. In the 11049A R1 is about 55Ω , in the 11050A R1 is about 65Ω , and in the




Figure 8. Selection of R1

11051A R1 is about 110Ω . The resistors used for R1 should be 1/2 watt, $\pm 5\%$, metal film resistors.

33. Figure 8 shows a bridge for selecting R1. R1 is adjusted for null with the drive voltage set so that the thermoelement operates at near rated full scale input. Proceed as follows.

- a. With the power supply off, construct the bridge shown in Figure 8.




Figure 9. Proper Orientation of Components

b. Connect an initial value of R1 as shown in Figure 8. For 11049A use two 120 Ω resistors in parallel; for 11050A use a 150 Ω and a 120 Ω resistor in parallel; for 11051A use two 220 Ω resistors in parallel.

c. Adjust drive voltage from power supply to the following value.

11049A	5.0 volts
11050A	1.5 volts
11051A	0.6 volts

Model 11049A

Page 10

- d. Vary R1 resistors to achieve a null indication on null meter. Maximum deviation from null should be as follows.

11049A	± 1.25 mV
11050A	± 0.375 mV
11051A	± 0.15 mV

A high value carbon resistor may be added in parallel with R1 as a final adjustment.

34. INSTALLATION OF THERMOELEMENT, R1, AND R2.

35. The spatial orientation of the components within the thermoelement is critical. Improper placing of the components may cause serious degradation of the higher frequency response. Figure 9 shows the proper component placement for each of the components in each thermal converter.

36. Observe the following precautions when installing replacement thermoelement and R1 and R2.




USE AN ADEQUATE HEAT SINK WHEN SOLDERING CONNECTIONS TO THERMOELEMENT. EXCESSIVE HEATING WILL CHANGE THERMOELEMENT CHARACTERISTICS.

- Keep all leads as short as possible.
- Make sure that component mounting matches that shown in Figure 9.
- Avoid bending thermoelement leads any more than is absolutely necessary. Excessive bending may weaken glass seal and reduce isolation.
- Red (positive) lead should be connected to thermoelement output lead with red dot.

37. REPLACEABLE PARTS.

38. Figure 10 shows the replaceable parts for the thermal converters. Included with each part is its -hp- part number, description, manufacturer, manufacturer's part number, and total quantity.



Ref. No.	-hp- Part No.	Description	Mfr.	Mfr. Part No.	TQ
1	1250-0045	Connector: male BNC	Dage Electric Co.	30337-2	1
2	2190-0016	Lock washer	Sloss and Brittain	1920-02	3
3	0360-0024	Lug: grounding	P. R. Mallory Co.	A-131023-1	2
4	2950-0001	Nut: hex, 3/8"	H. M. Harper Co.	Obd	1
5	0340-0039	Bushing: insulator	Goe Engineering Co.	HP-3000T-1	2
6	0340-0038	Terminal: output	Goe Engineering Co.	HP-3000M-3	2
	0853-0001	Thermoelement: UHF, 90 Ω 5 mA	Best Products Ltd.	UHF-5 mA	1
	11049-0002	Can: shield	-hp-	11049-0002	1
	11049-0003	Cover: top	-hp-	11049-0003	1
	2470-0001	Screw: machine hardware for top cover, no. 6/32 thread, brass	Schnitzer Alloy Prod. Inc.	Obd	2

Figure 10. Replaceable Parts

 **MANUAL CHANGES**

MODEL 11049A/11050A/11051A

-hp- Part Number 11049-90000

1. Model 11051A's with serial numbers 416-00275 and above have an added resistor R3 in series with the thermoelement input. R3 is made up of two 10 Ω , 1%, 1/8 W resistors (-hp- Part No. 0757-0346) in parallel and is added to adjust the nominal 7.5 mV output. R3 may not be present on all instruments; it is added only to adjust out-of-tolerance outputs.
2. On page 2, at bottom of page, change output relationship to

$$\% \text{ input change} = \frac{\Delta E_{dc}}{1.7E_{dc}} \times 100.$$

20 September 1968

11049-90000

MANUAL CHANNELS



ADDRESS: 100011 ADR - BERKOW

00000 10011 road, 11000 - 10000

Labbe m... and ...	100-0111 and with ...	10011 ...
... 100-0111 100-0111 100-0111 100-0111 ...
... 100-0111 100-0111 100-0111 100-0111 ...
... 100-0111 100-0111 100-0111 100-0111 ...

... 100-0111 ...

... 100-0111 ...

SALES AND SERVICE OFFICES

UNITED STATES and CANADA

ALABAMA

Huntsville, 35802
2003 Byrd Spring Rd. S.W.
(205) 881-4591
TWX: 510-579-2204

ALASKA

Bellevue, Wash. 98004
11656 N.E. 8th Street
(206) 454-3971
TWX: 910-443-2303

ARIZONA

Scottsdale, 85251
3909 No. Scottsdale Rd.
(602) 945-7601
TWX: 602-949-0111

Tucson, 85716
232 So. Tucson Blvd.
(602) 623-2564
TWX: 602-792-2759

CALIFORNIA

North Hollywood, 91604
3939 Lankershim Blvd.
(213) 877-1282 and 766-3811
TWX: 910-499-2170

Sacramento, 95821
2551 Carlsbad Ave.
(916) 482-1463
TWX: 916-444-8683

San Diego, 92106
1855 Shafter Street
(714) 223-8103
TWX: 714-276-4263

Palo Alto, 94303
1101 Embarcadero Rd.
(415) 327-6500
TWX: 910-373-1280

COLORADO

Englewood, 80110
7965 East Prentice
(303) 771-3455
TWX: 910-935-0705

CONNECTICUT

Middletown, 06457
589 Saybrook Rd.
(203) 346-6611
TWX: 710-428-2036

FLORIDA

Miami, 33125
2907 Northwest 7th St.
(305) 635-6461

Orlando, 32803
621 Commonwealth Ave.
(305) 425-5541
TWX: 305-841-2568

St. Petersburg, 33708
410-15th Ave., Madeira Beach
(813) 391-0211 and 391-1829
TWX: 913-331-0666

GEORGIA

Atlanta, 30305
3110 Maple Drive, N.E.
(404) 233-1341
TWX: 810-751-3283

HAWAII

North Hollywood, Calif. 91604
3939 Lankershim Blvd.
(213) 877-1282
TWX: 910-499-2170

ILLINOIS

Skokie, 60076
5500 Howard Street
(312) 677-0400
TWX: 910-223-3613

INDIANA

Indianapolis, 46205
3919 Meadows Dr.
(317) 546-4891
TWX: 317-635-4390

LOUISIANA

New Orleans
(504) 522-4359

MARYLAND

Baltimore, 21207
6660 Security Blvd.
(301) 944-5400
TWX: 710-862-9850

Rockville, 20852
12303 Twinbrook Pkwy.
(301) 427-7560
TWX: 710-828-9684

MASSACHUSETTS

Burlington, 01803
Middlesex Turnpike
(617) 272-9000
TWX: 710-332-0382

MICHIGAN

Southfield, 48076
24315 Northwestern Hwy.
(313) 353-9100
TWX: 313-357-4425

MINNESOTA

St. Paul, 55114
2459 University Ave.
(612) 646-7881
TWX: 910-563-3734

MISSOURI

Kansas City, 64114
9208 Wyoming Place
(816) 333-2445
TWX: 910-771-2087

St. Louis, 63144
2812 South Brentwood Blvd.
(314) 644-0220
TWX: 910-760-1670

NEW JERSEY

Easton town, 07724
(201) 747-1060

Englewood, 07631
391 Grand Avenue
(201) 567-3933
TWX: 510-230-9709

NEW MEXICO

Albuquerque, 87108
6501 Lomas Blvd., N.E.
(505) 255-5586
TWX: 910-989-1655

Las Cruces, 88001
114 S. Water Street
(505) 526-2406
TWX: 910-983-0550

NEW YORK

New York, 10021
236 East 75th Street
(212) 879-2023
TWX: 710-581-4376

Rochester, 14623
39 Saginaw Drive
(716) 473-9500
TWX: 510-253-5981

Poughkeepsie, 12601
82 Washington Street
(914) 454-7330
TWX: 914-452-7425

Syracuse, 13211
5858 East Molloy Rd.
(315) 454-2486
TWX: 710-541-0482

Endicott, 13764
1219 Campville Rd.
(607) 754-0050
TWX: 510-252-0890

NORTH CAROLINA

High Point, 27262
1923 N. Main Street
(919) 882-6373
TWX: 510-926-1516

OHIO

Cleveland, 44129
5579 Pearl Road
(216) 884-9209
TWX: 216-888-0715

Dayton, 45409
1250 W. Dorothy Lane
(513) 298-0351
TWX: 513-944-0090

OKLAHOMA

Oklahoma City
(405) 235-7062

PENNSYLVANIA

Camp Hill
(717) 737-6791

West Conshohocken, 19428
144 Elizabeth Street
(215) 248-1600 and 828-6200
TWX: 518-660-8715

Montcoeville, 15146
Monroe Complex
Building 2
Suite 2
Moss Side Blvd.
(412) 271-5227
TWX: 710-797-3650

TEXAS

Dallas, 75209
P.O. Box 7166, 3605 Inwood Rd.
(214) 357-1881
TWX: 910-861-4081

Houston, 77027
P.O. Box 22813, 4242 Richmond Ave.
(713) 667-2407
TWX: 713-571-1353

UTAH

Salt Lake City, 84115
1482 Major St.
(801) 486-8166
TWX: 801-521-2604

VIRGINIA

Richmond, 23230
2132 Spencer Road
(703) 282-5451
TWX: 710-956-0157

WASHINGTON

Bellevue, 98004
11656 N.E. 8th St.
(206) 454-3971
TWX: 910-443-2303

**GOVERNMENT
CONTRACTING OFFICE**

San Antonio, Texas 78226
Hewlett-Packard
Contract Marketing Division
225 Billy Mitchell Road
(512) 434-4171
TWX: 512-571-0955

CANADA

Montreal, Quebec
Hewlett-Packard (Canada) Ltd.
8270 Mayrand Street
(514) 735-2273
TWX: 610-421-3484
Telex: 01-2819

Ottawa, Ontario
Hewlett-Packard (Canada) Ltd.
1762 Carling Avenue
(613) 722-4223
TWX: 610-562-1952

Toronto, Ontario
Hewlett-Packard (Canada) Ltd.
1415 Lawrence Avenue West
(416) 249-9196
TWX: 610-492-2382

Vancouver, B.C.
Hewlett-Packard (Canada) Ltd.
2184 W. Broadway
(604) 738-7520
TWX: 610-922-5059

**For Sales and Service
Assistance in Areas Not
Listed Contact:**

EUROPE

Hewlett-Packard, S.A.
54 Route des Acacias
Geneva, Switzerland
Tel. (022) 42.81.50

ELSEWHERE

Hewlett-Packard
1501 Page Mill Road
Palo Alto, California 94304, U.S.A.
Tel. (415) 326-7000

