



**NOTES:**  
 1) FOR 220 VOLT OPERATION  
 CHANGE WIRING PER FIG. 4  
 AND REPLACE 3/4 AMP FUSE  
 WITH 3/8 AMP SLOW BLOW

Figure 3 Control Console Schematic