



POWER CONNECTOR SHOWN  
FROM SOLDER CONNECTION END

SCHEMATIC DIAGRAM  
MODEL L-4 PS POWER SUPPLY